U.S. Department of Housing and Urban Development
Office of Public and Indian Housing
2577-0274
02/28/2022

Status:	Draft	Approval Date:	Apj	proved By:			02/28/2022		
Part	Part I: Summary								
PHA Name : Brewer Housing Authority PHA Number: ME021			Locality (City/County & State)		Revised 5-Year Plan (Revision No:)		
А.	Development Number and	d Name	Work Statement for Year 1 2023	Work Statement for Year 2 2024	Work Statement for Year 3 2025	Work Statement for Year 4 2026	Work Statement for Year 5 2027		
	THE HERITAGE (ME021000001)		\$380,000.00	\$350,000.00	\$350,000.00	\$350,000.00	\$350,000.00		

1

Part II: Supporting Pages - Physical Needs Work Statements (s) Work Statement for Year 1 2023						
	THE HERITAGE (ME021000001)			\$380,000.00		
ID0014	Administration(Administration (1410)-Salaries)	Admin and maint wage and benefits		\$38,000.00		
ID0023	Replace Kitchen Cabinets (Dwelling Unit-Interior (1480)-Kitchen Cabinets)	Replace Kitchen Cabinets at 21-5		\$36,000.00		
ID0024	Replace Vinyl Siding (Dwelling Unit-Exterior (1480)-Siding)	Replace vinyl siding at 19B and 25 Chamberlain Street Scattered Sites		\$18,000.00		
ID0026	Replace Heritage Exterior Doors (Dwelling Unit-Exterior (1480)-Exterior Doors)	Replace 100 Exterior Doors		\$40,000.00		
ID0030	Replace all flooring (Dwelling Unit-Interior (1480)-Flooring (non routine))	Scattered Sites 20 Units		\$34,000.00		
ID0036	Operations(Operations (1406))	Operations BHA		\$80,000.00		

Part II: Supporting Pages - Physical Needs Work Statements (s)							
Work Statement for Year 1 2023							
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost			
ID0038	Replace Steps and Handrails Exterior(Dwelling Unit-Exterior (1480)-Stairwells - Fire Escapes)	Heritage 100, 200 and 300 buildings		\$36,000.00			
ID0044	Update Fire Alarm System (Non-Dwelling Construction - Mechanical (1480)-Security - Fire Alarm)	Update Fire Alarm System - Dartnell		\$50,000.00			
ID0063	Replace Roof 25 Chamberlain Street(Dwelling Unit-Exterior (1480)-Roofs)	Replace Roof 25 Chamberlain St, Scattered Sites		\$8,000.00			
ID0064	Replace Exterior Freeze Board and Trim(Dwelling Unit-Exterior (1480)-Other)	100, 200, 300, 400, & 500 Dartnell Apt		\$40,000.00			
	Subtotal of Estimated Cost			\$380,000.00			

Part II: Supporting Pages - Physical Needs Work Statements (s)							
Work State	Work Statement for Year 2 2024						
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost			
	THE HERITAGE (ME021000001)			\$350,000.00			
ID0015	Administration(Administration (1410)-Salaries)	Admin and Maint wage and benefits		\$35,000.00			
ID0032	Replace Vinyl Siding (Dwelling Unit-Exterior (1480)-Siding)	Replace Vinyl siding at Gerald D Robertson		\$90,174.00			
ID0037	Operations(Operations (1406))	Brewer Community Center		\$80,000.00			
ID0053	Replace Kitchen Cupboards(Dwelling Unit-Interior (1480)-Kitchen Cabinets)	21-7 & 21-8		\$87,000.00			
ID0060	Replace Sidewalks(Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving)	Norumbega Park 7 total		\$57,826.00			
	Subtotal of Estimated Cost			\$350,000.00			

Part II: Suj	Part II: Supporting Pages - Physical Needs Work Statements (s) Work Statement for Year 3 2025						
Work State							
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost			
	THE HERITAGE (ME021000001)			\$350,000.00			
ID0029	Replace Interior Doors (Dwelling Unit-Interior (1480)-Interior Doors)	Heritage and E. Charles Dartnell		\$22,200.00			
ID0040	Replace Vinyl Siding (Dwelling Unit-Exterior (1480)-Siding)	Replace Vinyl Siding at Norumbega III		\$61,800.00			
ID0047	Administration Salaries(Administration (1410)-Salaries)	Admin and Maint Salaries		\$35,000.00			
ID0048	Operations(Operations (1406))	Brewer Community Center		\$80,000.00			
ID0050	Replace Kitchen Cupboards (Dwelling Unit-Interior (1480)-Kitchen Cabinets)	Replace Kitchen Cupboards - Scattered Sites		\$96,000.00			
ID0061	Replace Kitchen / Livingroom Ceilings(Dwelling Unit-Interior (1480)-Other)	10 Units at Norumbega Park 400 & 500 buildings		\$18,000.00			

Part II: Sup	Part II: Supporting Pages - Physical Needs Work Statements (s)							
Work Statement for Year 3 2025								
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost				
ID0067	Replace rear decks(Dwelling Unit-Exterior (1480)-Decks and Patios)	Replace rear decks at 21-3		\$37,000.00				
	Subtotal of Estimated Cost			\$350,000.00				

Part II: Suj	Part II: Supporting Pages - Physical Needs Work Statements (s)						
Work Statement for Year 4 2026							
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost			
	THE HERITAGE (ME021000001)			\$350,000.00			
ID0052	Replace Gutters(Dwelling Unit-Exterior (1480)-Gutters - Downspouts)	21-5 & 341 N Main		\$2,000.00			
ID0054	Replace Windows(Dwelling Unit-Exterior (1480)-Windows)	21-4		\$60,000.00			
ID0055	Replace Kitchen Cupboards(Dwelling Unit-Interior (1480)-Kitchen Cabinets)	21-2 100 & 200 buildings		\$88,000.00			
ID0056	Admin Salaries(Administration (1410)-Salaries)	Admin Salaries		\$35,000.00			
ID0057	Operations(Operations (1406))	Operations		\$80,000.00			
ID0062	Replace Kitchen / Livingroom Ceilings(Dwelling Unit-Interior (1480)-Other)	Norumbega Park - 600 & 700 buildings / 10 units		\$18,000.00			

Part II: Sup	Part II: Supporting Pages - Physical Needs Work Statements (s)							
Work State	Work Statement for Year 4 2026							
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost				
ID0068	Replace Flooring (Dwelling Unit-Interior (1480)-Flooring (non routine))	Replace flooring at 21-9 20 units		\$40,000.00				
ID0069	Replace Bathroom tub / showers(Dwelling Unit-Interior (1480)-Tubs and Showers)	replace bathroom tub / showers 24-4 20 units		\$27,000.00				
	Subtotal of Estimated Cost			\$350,000.00				

Part II: Supporting Pages - Physical Needs Work Statements (s) Work Statement for Year 5 2027							
THE HERITAGE (ME021000001)			\$350,000.00				
Administrative (Administration (1410)-Salaries)	Salaries and Wages		\$35,000.00				
Operations(Operations (1406))	Operations		\$80,000.00				
Replace Flooring(Dwelling Unit-Interior (1480)-Flooring (non routine))	Replace flooring 21-5, 7 & 8 32 units		\$160,000.00				
Repair Foundations(Dwelling Unit-Exterior (1480)-Foundations)	repair foundations 21-4 19 Chamberlain St, 139 & 149 Church St		\$30,000.00				
Replace Decks(Dwelling Unit-Exterior (1480)-Decks and Patios)	Replace decks 21-4 341 North Main Street		\$15,000.00				
Replace swing sets and playground equipment(Non-Dwelling Site Work (1480)-Playground Areas - Equipment)	Replace swing sets and playground equipment 21-7		\$25,000.00				
	ment for Year 5 2027 Development Number/Name	ment for Year 5 2027 Development Number/Name General Description of Major Work Categories THE HERITAGE (ME021000001)	ment for Year 5 2027 Development Number/Name General Description of Major Work Categories Quantity THE HERITAGE (ME021000001) [] [] Administrative (Administration (1410)-Salaries) Salaries and Wages [] Administrative (Administration (1410)-Salaries) Salaries and Wages [] Operations(Operations (1406)) Operations [] Replace Flooring(Dwelling Unit-Interior (1480)-Flooring (non routine)) Replace flooring 21-5, 7 & 8 32 units [] Replace Flooring(Dwelling Unit-Exterior (1480)-Flooring (non routine)) repair foundations 21-4 19 Chamberlain St, 139 & 149 Church St [] Replace Decks(Dwelling Unit-Exterior (1480)-Flooring and Patios) Replace decks 21-4 341 North Main Street [] Replace wing sets and playground equipment (Non-Dwelling Site Work (1480)-Flagground Areas- Replace swing sets and playground equipment 21-7 []				

Part II: Sup	Part II: Supporting Pages - Physical Needs Work Statements (s)							
Work State	Work Statement for Year 5 2027							
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost				
ID0074	Replace Frost Proof Sillcocks(Non-Dwelling Exterior (1480)-Other)	Replace Frost Proof Sill cocks		\$5,000.00				
	Subtotal of Estimated Cost			\$350,000.00				